



PUBLIC WATER SYSTEM ANNUAL REPORT

-2007-

**TOWN OF BEAUSEJOUR
WATER WORKS DEPARTMENT**

General Office: (204) 268-7550

Water Works Shop: (204) 268-7561

Water Treatment Plant: (204) 268-7563

After Hours Emergency: (204) 268-7555

E-mail: townoffice@townofbeausejour.com

Date prepared:

December 2, 2008

Prepared by:

Glenn Steinke B.Sc. Honors
Director of Operations
Town of Beausejour

TABLE OF CONTENTS

1.0 Introduction	1
2.0 Purpose	1
3.0 Description Water Supply, Treatment, and Monitoring	1
3.1 Water Supply Source	1
3.2 Water Treatment	2
3.3 List of Water Quality Standards	3
3.4 Disinfection	5
3.5 Bacterial Monitoring Raw and Treated Water	6
4.0 Description Water Distribution System	6
5.0 Classification and Certification	7
6.0 Water System Incidents and Corrective Actions	8
7.0 Drinking Water Orders And Corrective Actions Taken	8
8.0 Boil Water Advisories Issued and Actions Taken in Response	8
9.0 Warning Issued or Charges Laid on the System in Accordance with Drinking Water Safety Act	8
10.0 Major Expenses Incurred	8
11.0 Future System Expansion and/or Increased Production	8

1.0 Introduction:

The operation of all public water systems in Manitoba is regulated in part by the “Drinking Water Safety Regulation (MR40/2007), which came into force on March 1, 2007. Section 32(1) of the Regulation (MR40/2007) requires all public water systems serving 1000 or more people to produce an annual report about the operation of the system.

2.0 Purpose:

The purpose of this annual report is to provide the residents of Beausejour:

1. Easy access to information related to the quality of the water they consume and the system that produces and transports to the taps in their homes.
2. Assurance that the quality of the water they consume meets all the requirements for aesthetic objectives as stated in the “Guidelines for Canadian Water Quality” and the health objectives consistent with the standards listed on the Public Water System Operating Licence PWS-08-203 issued by Manitoba Water Stewardship – Office of Drinking Water.
3. A report on the accountability of the Town of Beausejour to be in compliance with the regulatory requirements governing the provision of safe drinking water.
4. Answers to questions most often asked.

3.0 Description of the Water Supply, Treatment, & Monitoring

.1 Water Supply Source:

The Town of Beausejour draws water from the Lower Carbonate Aquifer, which lies approximately 70-80 feet below the ground surface. The major recharge for this aquifer is the Ross area south of Hwy. #15, south east of Beausejour. The Town has a Water Rights Licence #2005-023 that allows it to with draw up to 450 cubic decameters (364,82 acre feet) annually from the aquifer.

Three raw water supply wells have been drilled into this aquifer. All three wells are located on the Water Treatment Plant property at 914 Park Avenue. Well #1 was drilled in 1957 and is housed with-in the Water Treatment Plant building. This well was developed to produce water at a rate of 125 imperial gallons per minute. Well #2 was drilled in 1962 and is housed in a separate building in the south east corner of the property near Ashton Avenue. This well was developed to produce water at a rate of 200 imperial gallons per minute. Well #3 was drilled in 1995 and is housed in a separate building along the east side of the property about midway between Park Avenue and Ashton Avenue. This well was developed to produce water at a rate of 300 imperial gallons per minute.

Well #1 cannot supply enough water to meet the normal daily demand for water by the Town. It is exercised on a regular schedule and samples are drawn quarterly to ensure the water remains fresh and safe. It can be run in conjunction with Well #2 to supply raw water to the Treatment Plant in times of high demand.

Under normal operating conditions Wells #2 and #3 alternate to supply raw water to the Water Treatment Plant. The treated water is stored in the under ground reservoir. The level of water in the under ground reservoir controls the operation of the well pumps and the Water Treatment Plant to keep the level in the reservoir between 13 and 14 feet. During periods of high demand the Treatment Plant Controls are set so that either Well #3 is run or Well #1 and Well #2 are run together to supply water at higher rates.

.2 Water Treatment :

The original Water Treatment Plant was built in 1957 to house Well #1 and two pressure filters 5.5 feet in diameter, piping and related equipment. The two filters have a rated filter capacity of 125 gal per minute. In 1962 an addition was built onto the Water Treatment plant for two more pressure filters. A second addition to the Water Treatment Plant was built in 1976. This addition houses two more pressure filters bring the total number of filters to six for a rated total filter capacity of 375 gal. per minute. The reported rated capacity of the Treatment Plant is actually 300 imperial gallons per minute to allow for filter maintenance and in house water use. The 1976 addition included a separate room for the gas chlorination equipment.

As with all ground water source, the raw water Beausejour draws from the aquifer contains dissolved minerals and metals. With the exception of iron, the raw water meets all the drinking water standards as set out by the “ Guidelines for Canadian Drinking Water Quality” 6th Edition, 1996 including updates to April 1999.

Iron does not pose a health concern, but is listed under aesthetic water quality parameters. Iron can cause staining of laundry and plumbing fixtures. Iron can also cause build up of materials in the distribution piping reducing the overall capacity of the system.

The treatment process to remove iron from the raw water is a chemical free process. Compressed air is injected into the flow of water immediately up stream of the filters. The air is broken up into many tiny bubbles by what is called an atomerator. The atomerator distributes the bubbles uniformly through the water column. The oxygen in the air reacts with the dissolved iron to form a solid precipitate, which is removed by filtration. The iron precipitate is flushed out of the filters to waste during the regular backwash cycle. Excess air introduced to the water is vented through air bleed valves at the top of each filter.

Because the raw water is drawn from a carbonate aquifer it also contains considerable quantities of dissolved calcium carbonate. This causes the water to be considered hard. Evidence of the hardness can be seen by the soap ring in the sink after you wash your hands and the scale build up in kettles, coffee makers and hot water tanks.

The Beausejour water treatment process does not treat for hardness. Those people wishing to have the luxury of soft water for their laundry and baths can install their own individual water softeners. The modern water softeners have the ability to measure the water being treated by the unit and can determine the optimal time regenerate the ion exchange media. The Town recommends to home owners to set their softeners to 23 grains of hardness for the best results. The Town also recommends that after power outages the owners adjust their softener clocks to the correct time. Softeners are set to regenerate during the night when water is not normally being used. If they regenerate when water is in use they impart a salty taste to the water.

3 List of Water Quality Standards

Table #1 list the results of the analysis of Beausejour water samples to the Aesthetic Objectives as set by “Guidelines for Canadian Drink Water Quality. 6th Edition, 1996, updates to April 1999.

TABLE 1
TOWN OF BEAUSEJOUR
WATER QUALITY COMPARISON TO “GUIDELINE FOR CANADIAN DRINKING WATER”
FOR POTABILITY (Aesthetic Criteria) IN WATER

Conventional Parameters Aesthetic Criteria	Raw Water	Treated Water	Aesthetic Objective	Units
Total Dissolved Solids	476	453	500	mg/l
Dissolved Chloride Cl	55.6	55.8	250	mg/l
Dissolved Sulphate SO4	66.0	68.7	500	mg/l
ph, laboratory	7.39	7.37	6.5-8.5	ph units
Total Alkalinity CaCO3	314	308		mg/l
Bicarbonate Alkalinity HCO3	383	376		mg/l
Carbonate Alkalinity CO3	<0.5	<0.5		mg/l
Hydroxide Alkalinity OH	<0.5	<0.5		mg/l
Copper Cu	0.019	0.0062	1	mg/l
Iron Fe	1.04X	0.05	0.3	mg/l
Manganese Mn	0.02	0.014	0.05	mg/l
Zinc Zn	0.035	0.003	5	mg/l

mg/l = milligrams per liter

< = Less than detection limit

X = result is outside the aesthetic limit

Table #2 lists those water quality standards for a ground water supply source adopted by the Province of Manitoba from the “Guidelines for Canadian Drinking Water Quality 6th Edition, 1996, including updates to April 1999 developed by Health Canada. For the parameters tested, results are categorized by health concerns. Any parameter in excess of the maximum accepted concentration, constitute a health related issue and require corrective action.

TABLE 2 For the Year **2007**
TOWN OF BEAUSEJOUR
WATER QUALITY COMPARISON TO PWS-08-203 LICENCE WATER QUALITY STANDARDS
FOR POTABILITY (Health Criteria at point of Use) IN WATER

Conventional Parameters Health Criteria	Quality Standard	Test Frequency	Test Results	Units
Total Coliform & Ecoli	No TC & EC	Bi-weekly	100% Passed	per 100ml
Chlorine Residual	>0.5 WTP Distribution (0.1)	Daily	100% Compliance	mg/l
		Periodically	100% Compliance	mg/l
Dissolved Fluoride F	1.5	One Raw & One Treated Sample every three Years	0.36	mg/l
Nitrate and Nitrite N	10		0.15	mg/l
Arsenic As	0.025		0.0006	mg/l
Lead Pb	0.01		0.0004	mg/l
Uranium U	0.02		0.0004	mg/l
Trichloroethylene	0.005		0	mg/l
Tetrachloroethylene	0.03		<	mg/l
Benzene	0.005		Not Tested	mg/l

mg/l = milligrams per liter
 < = less than detection limit

The results in Tables #1 and #2 are from the analysis of water samples collected by Manitoba Water Stewardship – Office of Drinking Water in October of 2005. The analysis was performed by CANTEST Ltd. on their behalf.

.4 Disinfection:

The final step in the water treatment process is disinfection. Disinfection is defined as the selective destruction or inactivation of potential disease causing organisms in water. The chemical most commonly used is chlorine. The “Drinking Water and Safety Act “ requires that a disinfectant residual level of at least:

- 0.5 mg of free chlorine per liter of water is detectable at the point where water enters the distribution system, after a minimum contact time of 20 minutes.
- 0.1 mg of free chlorine per litre of water is detectable at all times at any point in the distribution system.

The Town of Beausejour uses chlorine gas to disinfect the water. Chlorine in a gaseous form is injected at rate determined by the pumping rate of each pump through an injector into a separate stream of water under distribution system pressure. This stream of water/chlorine is then injected into the treated water as it leaves the water treatment plant for storage in the under ground reservoir.

The “Drinking Water and Safety Act” requires that disinfection is continuously maintained. The Town of Beausejour operates two chlorinators each mounted separately on its own 68kg tank of chlorine gas. Normally only one chlorinator is in operation at any time. Once its tank runs empty the system switches over to the other chlorinator automatically. In this manor one chlorinator is in reserve back up at all times. The Town also keeps a stock of spare parts required for the chlorination system as well as a complete new chlorinator.

The “Drinking Water Safety Act” requires that the disinfection residuals are monitored daily at the water treatment plant and periodically at various points in the distribution system and recorded on the appropriate monitoring forms. These forms are sent to the regional “Drinking Water Officer” at the end of each month. Table 3 records the results of the Provincial Annual audit for 2007.

Table 3 Disinfection Monitoring and Reporting

	Regulatory Requirement	PWS Performance
Free chlorine residual entering the distribution system Section 21(1) a – MR 40/2007	≥ 0.5 mg/L	100 %
Free chlorine residual in the distribution system Section 22 a – MR 40/2007	≥ 0.1 mg/L	100 %
Frequency of testing Schedule A – MR 40/2007	Daily	100 %
Report submissions Section 25(2) – MR 40/2007	Monthly	100 %
<u>Comments:</u> The Public Water System has met their regulatory requirements for 2007.		

. 5 Bacterial Monitoring of Raw and Treated Water

As per Provincial regulatory requirements, every two weeks the Town collects three samples; one from the raw water entering the water treatment plant(Note: Samples are alternated between wells #2 & #3, and an extra sample is submitted for well#1 when required.), one from treated water leaving the water treatment plant, and one of the water from the distribution system, and submits them to the ALS Laboratory to test for the presence or absence of Total Coliform Bacteria and E-Coli Bacteria. Table 4 records the results of the Provincial Annual Audit for 2007.

Table 4 Bacteriological Monitoring and Reporting

	Regulatory Requirement	Beausejour Public Water System Performance
Number of raw/incoming water samples <small>Schedule A – MR 40/2007</small>	26	100%
Number of treated water samples <small>Schedule A – MR 40/2007</small>	26	100%
Number of distribution water samples <small>Schedule A – MR 40/2007</small>	26	100%
Frequency of testing <small>Schedule A – MR 40/2007</small>	bi-weekly	100%
Total Coliform present in samples <small>Section 3(1) a – MR 41/2007</small>	0 TC per 100mL	100%
E – Coli present in samples <small>Section 3(1) a – MR 41/2007</small>	0 EC per 100mL	100%
<u>Comments:</u> The Public Water System has met their regulatory requirements for 2007.		

4.0 Description of Water Distribution System:

Water leaving the Treatment Plant is stored in the concrete underground reservoir located immediately to the south of the plant. The reservoir capacity is 750,000 gallons. Under normal water use this approximately three days of reserve supply.

Two 25 horsepower service pumps alternate to supply water to the distribution system. Excess water pumped to the distribution system is stored in the Water Tower (Elevated Reservoir). The Water Tower has a storage capacity of 62,500 gallons. The water level in the tower controls the operation of the service pumps and supplies the water pressure to the distribution system. The normal range of operation for the water tower level is 85 to 97 per cent. This represents a variance of approximately one half pound per square inch of water pressure. At the base of the Water Tower the pressure is 43 pounds per square inch.

The water distribution system is made up 27,728 meters of water main piping ranging from 1” up to 10”. The 10” and 8” water mains serve as arterial branches while the majority of the piping is predominately 6” in diameter. The system is complimented by 162 fire hydrants and 218 main valves. 69 % of the piping material is cast or ductile iron installed between 1957 and 1985. The remaining 31% of piping material is PVC plastic pipe installed after 1985.

5.0 Classification and Certification:

Regulations M.R. 77/2003 and M.R. 162/2005 under the Environment Act(C.C.S.M. c. E125) regulate the Classification of all Water or Wastewater Facilities and the Certification of all Water and Wastewater Facility Operators in Manitoba.

All Water and Wastewater Facilities were required to make application for Classification before January 3, 2006. The Classification for Beausejour Water Treatment (WT) and Water Distribution (WD) is Class I WT (Iron Removal); Class II WD.

As of September 1, 2006 all owners of Water and Wastewater Systems must employ only Provincially Certified Operators. The two Operators assigned to the Water Works Department are Certified as follows:

Soren Thogersen	Lead Hand Utility	WT Class I	WD Class II
Darryl Mazur		WT Class I	WD Class II

In addition to the Operators normally assigned to the Utility, the Town of Beausejour requires all other operators in Works and Operations to have or obtain Provincial Certification. The Certification level of the other staff in Works and Operations is as follows:

Glenn Steinke	Director of Operations	WT Class II	WD Class III (Conditional)
Allan Murash	Lead Hand Public Works	WT Class II	WD Class II
Andy Severinsen		WT Class II	WD Class II (Conditional)
Dave Brown		WT Class I	WD Class I (Conditional)

The Town continually supports its Operators by sending them to training Courses and Seminars. All new and existing staff receive the necessary training and related education to write the required examinations to obtain their Provincial Operators Certification.

The Town continues to maintain an Operator On-Call Program. Works and Operations Operators rotate to take on On-Call duties. To report an emergency to the Town please call (204)268-7555 and leave a message. The Operator On-Call will be paged and alerted to the emergency.

6.0 Water System Incidents and Corrective Actions :

Incident 1: Clean Sand Well #3

When the well pumps were pulled for serving in 2006 it was found that sand had accumulated at the bottom of well #3 to the point that a cleaning was recommended. Maple Leaf Services were hired to pull the well pump and air-lift the sand accumulation out of the well. The well was cleaned from approximately 90 feet down to 120 feet. As we had advance notice the work could be scheduled.

Incident 2: Service Leak 1024 Park Avenue

A leak was detected in the service line to 1024 Park Avenue. A new service line was directionally bored under the service road to connect the existing line on the property to the water main. Only the business at 1024 Park Avenue was affected. (Note: The portion of the water service from the water main to the property line is the Towns responsibility for maintenance/repair. Any portion of the water service line including the connection to the curb stop valve from the property to the building is the owners responsibility.)

7.0 Drinking Water Orders and Corrective Actions Taken:

In 2007, no Drinking Water safety Orders were issued.

8.0 Boil Water Advisories Issued and Actions Taken in Response:

In 2007, no Boil Water Advisories were issued.

9.0 Warnings Issued or Charges Laid on the System in Accordance with The Drinking Water Safety Act:

No charges or warnings were issued. An extension in time was granted to prepare the Annual Water Report.

10.0 Major Expenses Incurred:

The cost to clean Well #3 was \$2,300. \$10,000 had been budgeted.

The cost to replace the service line from the street to the property at 1024 Park Avenue \$3,800, which was covered in the Operating Budget.

11.0 Future System Expansion and/or Increased Production:

In 2007, \$10,500 was budgeted for an Engineering Evaluation/Assessment of the Water Supply and Treatment portion of the Utility. Only, \$3,160 was actually spent. For the 2008 Budget year an additional \$10,500 has been allocated for the Engineering Evaluation/Assessment, which is to be complete by March 31, 2008 as required by the Public Water System's Operating Licence. Long range plans involving up-grading, replacement, expansion, and adequate funding will be developed once the Engineering Assessment has been completed.